

Here is the calibration procedure:

- 1) turn the mod wheel all the way off (down), and while also holding the pitch wheel off, hold the Reset switch and hit the keypad 4 switch.
- 2) Return the pitch wheel to center, and hold Reset and hit 5.
- 3) Move the Mod wheel all the way on (up), and while also holding the pitch wheel all the way on, hold Reset and hit the 6 switch.

Let us know if you still have problems!

Cheers,

Dave